

Over and Above Estimate

Region: 4

Location: WV006

CSS #: 17372

Maximo Work Order No.: 8132

Asset#: NA

Date Issued: 2/20/19

Original Description: The Utility Heater In-Between The Crane Bay and Bay #1 INOP

Diagnosis: Investment is labor and materials to replace the gas hanging heater in the Motor Pool due to a failed heat exchanger, located at USARC Cross Lanes WV006, CSS# 17372. The existing heater is obsolete, parts are not available

Non Pre-Priced Estimate:

Quantity	Line Item Number	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		GTNE004 Gas Heater, Trane				\$834.34		\$834.34
1		Shipping and Handling				\$162.50		\$162.50
1		Trip Charge				\$35.00		\$35.00

1		Miscellaneous Parts				\$60.00		\$60.00
---	--	---------------------	--	--	--	---------	--	---------

Note: RS Means (Pre-Priced) not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment Cost	Total Cost	CE Factor	Total Estimate
Mechanic- 8 x \$115= \$920.00 Apprentice- 8 x \$93= \$744.00	\$1,664.00	\$1,091.84		\$2,755.84	102%	\$2,810.96

Please see attached estimate

Note:

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: crosslanes Date of Visit: 3/4/2019

Contractor Personnel on Site:

1. Lewis Michael 2. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO# 156862

Service Calls – Service Call Number and Description

1. CSS# 17372
2. CSS# _____
3. CSS# _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Lewis Michael Date: 3/4/2019

Signed: 

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: meadows,dorin Date: 3/4/2019

Signed: 

E-Mail: _____

