



Transformer located in mechanical room of ARC is buzzing very loud and is very close to reaching end of life cycle. If transformer fails, a large part of the electric supply for this facility will be lost. Request is for vendor to troubleshoot and repair/replace as necessary.

Material & Labor to complete the following repair.

Replace 75KVA transformer located in the Mechanical Room.

Will require scheduling with AFOS. When this transformer is taken out of service, the boiler system and server will be down along with many other 120/208 volt utilities. The outage should last 3 – 4 hours.

CMI Cost Estimate								
Over & Above								
WV053 Wheeling								
Transformer located in mechanical room								
CSS #17008 - CMI # 7157								
Prepared By: J. Bayne								
1.04.19								