

Over and Above Estimate

Region: 4

Location: WV046

CSS #: 15495

Maximo Work Order No.: 5940 **Asset#:** NA

Date Issued: 10/05/18

Original Description: Replace Bumpers

Diagnosis:

- 1: Remove existing Loading Dock Bumpers
- 2: Clean existing surface
- 3: Drill and anchor concrete for metal brackets
- 4: Install New Bumpers and secure solid in place

Non Pre-Priced Estimate:

Quantity	Line Item Number	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
2		Bumpers				\$1,994.00		\$1,994.00

Note: RS Means (Pre-Priced) not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment Cost	Total Cost	CE Factor	Total Estimate
19.5 hours x 100	\$1,950	\$1,994		\$3,944.00	102%	\$4,073.88

Please see attached estimate

Note:

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: WV046 Date of Visit: 10-16-18

Contractor Personnel on Site:

1. Derek Jones 2. _____


Work Performed: Replace Bumpers on Loading Dock INITIAL INSPECTION FOR AWUE

Preventive Maintenance - (Annual, Quarterly, Monthly, equipment identification, etc.)
Service Orders - CSS# 15495

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Derek Jones Date: 10/16/18

Signed: 

To be signed by Facility Manager:

I certify that the above-named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: 1SG Gillenwalters Tom Date: 16 OCT 18

Signed: Timothy Silkenwalters

E-Mail: timothy.n.gillenwalters.cid@mail.mil