

Date: 4-10-24

Region: 4A

CSS No.: 96886

FAC ID: PA027

Maximo WO No.: 15191

Asset #: [ ]

Priority: 2



**Original Work Request:**

Replace/Repair two emergency exit signs in the supply area, cage area for 475th supply and 347th QM Group. Also light in Hazmat storage outside OMS needs to be replaced.

**Description of Repairs Needed:**

Replace two emergency exit signs. One sign does not have power and will require wiring to install. Quote to include running wire to one of the new exit signs, along with replacing the light in the Hazmat storage room.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	3	\$ 100.00	\$ 300.00
			\$ -

**Material List:**

	Quantity	Cost	Total
1/2" EMT piping (3 ft needed)	3	\$ 20.94	\$ 62.82
clamps/couplings/connectors	1	\$ 15.00	\$ 15.00
12 awg THHN Wire (Black)	1	\$ 28.35	\$ 28.35
12 awg THHN Wire (White)	1	\$ 28.35	\$ 28.35
conduit bender	1	\$ 39.97	\$ 39.97
Exit light (H-1663)	2	\$ 50.00	\$ 100.00
			\$ -

**Equipment List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$300.00	\$274.49	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$574.49	\$68.94	\$34.47	\$677.90