

Date: 4-01-25

Region: 4A

FAC ID: PA027

FEMS/CSS No.: 2935194

Maximo WO No.: 18506

Asset #:

Priority: 2



**Original Work Request:**

Repair 4 door refrigerator in the kitchen. Refrigerator is at 54 degrees and the compressor is very hot. This facility is a field feeding team location and utilizes the kitchen.

**Description of Repairs Needed:**

Proposal is to repair 4 door refrigerator in kitchen. Repair includes replacing compressor, motor, evacuating refrigerant and recharging.

Labor:	Labor Hrs	Labor Rate	Total
Tech (1)	6	\$ 100.00	\$ 600.00
			\$ -
			\$ -

Material List:	Quantity	Cost	Total
AE4430Y Condensing unit 1/4HP, 115V	1	\$ 697.54	\$ 697.54
R134 (30#)	1	\$ 417.97	\$ 417.97
GSTWIN Appion Recovery Machine	1	\$ 944.50	\$ 944.50
Bullet DC 7CFM /Vac 2 stage	1	\$ 671.97	\$ 671.97
Brazing Alloy 15% 28 sticks/tube	1	\$ 190.61	\$ 190.61
Swivel Tee 3pk 1/4 SAE w/ DEPR	1	\$ 24.52	\$ 24.52
010-1409 Ranco Temp Ctrl, SPST	1	\$ 116.48	\$ 116.48
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

**PM WO History:**

**Estimate Summary:**

Labor	Material	Equipment
\$600.00	\$3,063.59	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$3,663.59	\$439.63	\$219.82	\$4,323.04