

Date: 3-11-2025

Region: 4A

FEMS/CSS No.: 3071337

FAC ID: PA027

Maximo WO No.: 18305

Asset #:

Priority: 2



Original Work Request:

No heat in lactation room. Repair the radiant heat in the room. The room is currently being used by a soldier.

Description of Repairs Needed:

Repair HVAC system feeding the Lactation Room. Scope of work include drain system, install valves, refill system, bleed out all air and startup and check for proper operation

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	16	\$ 170.00	\$ 2,720.00
Trip Charge	1	\$ 74.00	\$ 74.00
			\$ -

Material List:

	Quantity	Cost	Total
3/4"valves	2	\$ 47.50	\$ 95.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$2,794.00	\$95.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,889.00	\$346.68	\$173.34	\$3,409.02