

Date: 7-30-25

Region: 4A

FEMS/CSS No.: 3265410

FAC ID: PA027

Maximo WO No.: 19796

Asset #:

Priority: 2



Original Work Request:

Tree has fallen on the fence around the MEP, tree needs to be removed and fence repaired. Facility has aPhysical Security Inspection the first week of September.

Description of Repairs Needed:

Proposal is the remove down tree and repair fence.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	8	\$ 62.54	\$ 500.35
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
fence ties and shop supplies	1	\$ 40.00	\$ 40.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$500.35	\$40.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$540.35	\$64.84	\$32.42	\$637.61