

Date:

Region:

CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



**Original Work Request:**

Repair the swivel joint on the hose reel for the air compressor located in the OMS bldg.

**Description of Repairs Needed:**

Checked hose reel, requested staff to check warranty. Determined no longer under warranty and received quote to replace with new 50' COXREELS spring return hose reel.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	2.5	\$ 100.00	\$ 250.00
			\$ -

**Material List:**

	Quantity	Cost	Total
Spring Return Hose Reel, 3/8" MNPT, (P-LP-350-RH-BXB)	1	\$ 547.46	\$ 547.46
Misc supplies	1	\$ 25.00	\$ 25.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

**Equipment List:**

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

**PM WO History:**



**Estimate Summary:**

Labor	Material	Equipment
\$250.00	\$572.46	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$822.46	\$98.70	\$49.35	\$970.50