

Date: 04-09-25

Region: 4A

FEMS/CSS No.: 3113846

FAC ID: PA035

Maximo WO No.: 18529

Asset #:

Priority: 1



Original Work Request:

Repair overhead door in the Training Center as it has loose cables, and the wheel is out of the track. Door is not usable at this time, and the unit needs to use this to get their equipment ready and packed for annual training at the beginning of April. Will need to be completed before April 4.

Description of Repairs Needed:

Proposal is to repair overhead door prior to April 4. Assessment/repair discovered rollers out of track. Repair is to place roller back in, perform general repairs on door system and reset limits. Test and ensure door is operating properly.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	4	\$ 98.06	\$ 392.25
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
Materils (shop supplies)	1	\$ 12.34	\$ 12.34
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$392.25	\$12.34	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$404.59	\$48.55	\$24.28	\$477.42