

Date: 2-18-26



Region: 4A

FEMS/CSS No.: 3462644

FAC ID: PA035

Maximo WO No.: 20965

Asset #:

Priority: 1

Original Work Request:

Contactor on the air compressor is burnt up and need to be replaced.

Description of Repairs Needed:

Proposal is to replace the compressor contactor, start up and check for proper operation.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	8	\$ 179.00	\$ 1,432.00
Trip Charge	1	\$ 60.00	\$ 60.00
			\$ -

Material List:

	Quantity	Cost	Total
Contactor (8911DPSG42V09)	1	\$ 390.00	\$ 390.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,492.00	\$390.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,882.00	\$225.84	\$112.92	\$2,220.76