

Date: 2-14-2025



Region: 4A
FAC ID: PA062

FEMS/CSS No.: 3031268
Maximo WO No.: 18258

Asset #:

Priority: 3

Original Work Request:

Replace 3 CAC card readers with two on the Training Bldg and one on the OMS Bldg. Repair Training Bldg interior and exterior AI phone system to work with card readers and alert when someone is at the door.

Description of Repairs Needed:

Replace (3) biometric card readers with new - (2) in Training Bldg and (1) in the OMS Bldg.

Labor:	Labor Hrs	Labor Rate	Total
Tech (1)	8	\$ 95.00	\$ 760.00
Administration	1	\$ 100.00	\$ 100.00
			\$ -

Material List:	Quantity	Cost	Total
Biometric Card Readers (Sigma Lite, 293678678)	3	\$ 1,550.00	\$ 4,650.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$860.00	\$4,650.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$5,510.00	\$661.20	\$330.60	\$6,501.80