

Date: 8-22-24

Region: 4A

FAC ID: PA062

CSS No.: 98854

Maximo WO No.: 16607

Asset #:

Priority: 3



Original Work Request:

Crane at this location is not on the PM inventory and needs to be annually inspected.

Description of Repairs Needed:

Annual OSHA preventative maintenance inspection of crane and hoist system. Service is to lubricate all grease points, fill gearboxes, adjust brakes and limit switches, tighten any loose bolts, check all electrical contactors and mechanical functions and verify compliance with OSHA.

Labor:	Labor Hrs	Labor Rate	Total
Tech (2)	10	\$ 97.50	\$ 975.00
			\$ -

Material List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$975.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$975.00	\$117.00	\$58.50	\$1,150.50