

Date: 3-25-26



Region: 4A

FEMS/CSS No.: 3576697

FAC ID: PA062

Maximo WO No.: 21626

Asset #:

Priority: 2

Original Work Request:

While Grunau was on site for the fire panel issues they found the following: Batteries failed Load test will need two 12v 7AH batteries

Description of Repairs Needed:

Replace batteries failing load test

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)-- Includes 3 hr Travel Time	8	\$ 154.00	\$ 1,232.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
12V 7 AMP batteries	2	\$ 55.00	\$ 110.00
freight	1	\$ 45.00	\$ 45.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,232.00	\$155.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,387.00	\$166.44	\$83.22	\$1,636.66