

Date: 4-23-24

Region: 4A
FAC ID: PA063

CSS No.: 93144
Maximo WO No.: 15221

Asset #:

Priority: 3



Original Work Request:

Repair floor drainin the mechanical room. Floor drain for the boilers is falling apart and it appears the floor will need to be cust and a new drain and drain pipe installed.

Description of Repairs Needed:

Proposal is to replace the floor drain at New Castle facility. No additional work is implied other than what is specifically stated and identified in the proposal.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1) investigate repair	2	\$ 148.00	\$ 296.00
Tech (2) complete repair	48	\$ 148.00	\$ 7,104.00

Material List:

	Quantity	Cost	Total
Backwater Valve (869-S3PS)	1	\$ 95.00	\$ 95.00
Drain (FD-100-A)	1	\$ 234.00	\$ 234.00
PVC Pipe	1	\$ 84.00	\$ 84.00
Concrete Patching	1	\$ 75.00	\$ 75.00
Saw Cutter	1	\$ 60.00	\$ 60.00
Trip Charge -	1	\$ 200.00	\$ 200.00
			\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$7,400.00	\$748.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$8,148.00	\$977.76	\$488.88	\$9,614.64