

Date: 7/27/2023

Region: 4A  
FAC ID: PA063

CSS No.: 94374  
Maximo WO No.: 13605

Asset #:

Priority: 2



**Original Work Request:**

Repair split unit in the supply office of Rm 121 as it is not cooling. Air is coming from the unit, but is blowing warm.

**Description of Repairs Needed:**

Proposal to replace split unit that is dated and parts no longer available. Recently recharged the unit, it has leaks and parts are no longer available. Recharging the unit was a temporary fix only.

**Labor:**

	Labor Hrs	Labor Rate	Total
1 Tech	2.5	\$ 147.00	\$ 367.50
			\$ -

**Material List:**

	Quantity	Cost	Total
2# R410A Refrigerant	2	\$ 24.00	\$ 48.00
Fuel Charge	1	\$ 50.00	\$ 50.00
Truck Fee	1	\$ 50.00	\$ 50.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**Equipment List:**

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**PM WO History:**



**Estimate Summary:**

Labor	Material	Equipment
\$367.50	\$148.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$515.50	\$61.86	\$30.93	\$608.29