

Date: 8-23-24

Region: 4A
FAC ID: PA063

CSS No.: 98855
Maximo WO No.: 16608

Asset #:

Priority: 3



Original Work Request:

Crane at this location is not on the PM inventory and needs to be inspected

Description of Repairs Needed:

Annual OSHA preventative maintenance inspection of crane and hoist system. Inspect all components for OSHA violations, operational conditions and potential maintenance problems. Lubricate all grease points, fill gearboxes, adjust brakes and limit switches, tighten any loose nuts/bolts, check contactors and mechanical functions, verify compliance with OSHA.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	9.07	\$ 97.50	\$ 884.33
			\$ -

Material List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$884.33	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$884.33	\$106.12	\$53.06	\$1,043.50