

Date: 7-05-24

Region: 4A

CSS No.: 97481

FAC ID: PA118

Maximo WO No.: 16145



Asset #: [Redacted]

Priority: 3

Original Work Request:

Repair the drop down exhaust hoses located in the work bays. AMSA has approximately 9 exhaust drop down exhaust hoses that need to be repair/replaced and two to be repaired. Warehouse has one that needs to be repaired.

Description of Repairs Needed:

Follow up to WO #15612...additional hoses needed to complete seven (7) remaining units. Hoses only come in 25' sections and it requires connecting two hoses for each remaining section. Lift is required to replace the exhaust hoses and it is recommended for a temporary dumpster to be placed on site for disposal in order to not impact facility operations.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	16	\$ 100.00	\$ 1,600.00
			\$ -

Material List:

	Quantity	Cost	Total
Ducting Hose, 8"x25' (3WB19)	14	\$ 491.00	\$ 6,874.00
Duct Hose Bridge Clamps, 31" (RH, 304SS)	14	\$ 17.79	\$ 249.06
Connecting Pipe, 8"-30ga 24" (8H624)	7	\$ 10.89	\$ 76.23
Freight	1	\$ 250.00	\$ 250.00
Misc (shop supplies, straps, screws, etc)	1	\$ 50.00	\$ 50.00
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
Lift (30-33' Electric Scissor)	1	\$ 750.00	\$ 750.00
20" Dumpster (Waste Mgmt)	1	\$ 1,200.00	\$ 1,200.00
			\$ -

PM WO History:

[Redacted]

Estimate Summary:

Labor	Material	Equipment
\$1,600.00	\$7,499.29	\$1,950.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$11,049.29	\$1,325.91	\$662.96	\$13,038.16