

Date: 8-13-24

Region: 4A

CSS No.: 98702

FAC ID: PA118

Maximo WO No.: 16399

Asset #:

Priority: 2



Original Work Request:

Pump approximately 10,000 gallons from the water tank of the oil/water separator and water tank that is located between the AMSA and Wash Rack.

Description of Repairs Needed:

Propose to furnish the equipment and perform the following services. Pump water/solids from tank between AMSA and Wash Rack. Quote based on 10,000 gallons of unknown materials between liquids and solids.

Labor:

	Labor Hrs	Labor Rate	Total
Truck/Labor Fee	1	\$ 425.00	\$ 425.00
			\$ -

Material List:

	Quantity	Cost	Total
Liquid Disposal = \$1.50/gal	10000	\$ 1.50	\$ 15,000.00
Solids Disposal = \$3.75/gal	1313.4	\$ 3.75	\$ 4,925.25
Energy Surcharge = 7% of total bill	1	\$ 1,074.75	\$ 1,074.75
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$425.00	\$21,000.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$21,425.00	\$2,571.00	\$1,285.50	\$25,281.50