

Date: 7/19/2023

Region: 4A  
FAC ID: PA118

CSS No.: 94015  
Maximo WO No.: 13370

Asset #:

Priority: 2



**Original Work Request:**

Warehouse compressor needs to have an auto drain installed on it as there is no way for the system to release the water from the compressor and is causing issues. This was determined when the PM was performed.

**Description of Repairs Needed:**

Replace auto drain valve and test operations

**Labor:**

	Labor Hrs	Labor Rate	Total
1 tech	1.5	\$ 100.00	\$ 150.00
			\$ -

**Material List:**

	Quantity	Cost	Total
Auto Drain Valve (100-120V,3/8", Manufacturer #13X526)	1	\$ 132.24	\$ 132.24
shop supplies	1	\$ 15.00	\$ 15.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**Equipment List:**

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$150.00	\$147.24	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$297.24	\$35.67	\$17.83	\$350.74