

Date: 12-21-23

Region: 4A

CSS No.: 96062

FAC ID: PA118

Maximo WO No.: 14549



Asset #: []

Priority: [] 3

Original Work Request:

Repair air compressor located in the warehouse. The ball valve shut off on the air line is not working to shut the air off from the air compressor. Also an attachment is needed for the hose line

Description of Repairs Needed:

Replace air compressor hose reel with new COXREELS spring return hose reel, 3/8" MNPT, 75 ft.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	3.5	\$ 100.00	\$ 350.00
			\$ -

Material List:

	Quantity	Cost	Total
Spring Return Hose Reel (EZ-SH-375)	1	\$ 784.44	\$ 784.44
Misc materials	1	\$ 25.00	\$ 25.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
Lift Rental	1	\$ 820.33	\$ 820.33
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$350.00	\$809.44	\$820.33

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,979.77	\$237.57	\$118.79	\$2,336.13