

Date:

Region:

CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



Original Work Request:

Perform PM on the Landa wash rack recycler to include cleaning the water lines and flow gauges serviced and cleaned and backwashing the system. Recommended Vendor: Jim Lucas (724) 625-3544. This would be the only vendor in the area that is certified and qualified to service this type system.

Description of Repairs Needed:

Go over recycle system, clean flow meters manually and backflush system and test pH levels

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	4	\$ 125.00	\$ 500.00
Travel	1	\$ 240.00	\$ 240.00

Material List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$740.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$740.00	\$88.80	\$44.40	\$873.20