

Date:

Region:

CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



Original Work Request:

Repair bay door #2. The door will not close the entire way down to the floor.

Description of Repairs Needed:

Loose coupler with keyway worked out. Will need to replace coupler and key and then test operations.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	4	\$ 115.50	\$ 462.00
			\$ -

Material List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

Equipment List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$462.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$462.00	\$55.44	\$27.72	\$545.16