

Date: 4-11-24

Region: 4A  
FAC ID: PA118

CSS No.: 97385  
Maximo WO No.: 15421

Asset #:

Priority: 2



**Original Work Request:**

Repair trench drains and ensure proper flow to OWS

**Description of Repairs Needed:**

Proposal to collect and provide laboratory analysis of waste materials in the trench drain for proper disposal. Once lab analysis is received and the materials properly classified, a proposal for the actual cleaning and removal will be submitted under a separate proposal.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1) - collect/send for lab analysis of trench waste	1	\$ 776.25	\$ 776.25
			\$ -

**Material List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

**Equipment List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

**PM WO History:**



**Estimate Summary:**

Labor	Material	Equipment
\$776.25	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$776.25	\$93.15	\$46.58	\$915.98