

Date: 4-29-24

Region: 4A

FAC ID: PA118

CSS No.: 97481

Maximo WO No.: 15429

Asset #:

Priority: 3



Original Work Request:

Repair the drop down exhaust hoses located in the work bays. AMSA has approximately nine drop down exhaust hoses that need to be repaired/replaced and two to be repaired. Warehouse has one that needs to be repaired.

Description of Repairs Needed:

Proposal is to replace exhaust hoses in the work bays, AMSA and Warehouse. A total of 12 exhaust hoses identified for replacement, will require purchase of 14 based on length of the hoses. Service request will require the use of a lift to complete task.

| Labor: | Labor Hrs | Labor Rate | Total |
|----------|-----------|------------|-----------|
| Tech (1) | 8 | \$ 100.00 | \$ 800.00 |
| | | | \$ - |

| Material List: | Quantity | Cost | Total |
|---|----------|-----------|-------------|
| Ducting Hose 8" ID x 25' (part #1110-0800-0002) | 14 | \$ 472.00 | \$ 6,608.00 |
| | | | \$ - |
| | | | \$ - |
| | | | \$ - |
| | | | \$ - |
| | | | \$ - |
| | | | \$ - |

| Equipment List: | Quantity | Cost | Total |
|-----------------|----------|-----------|-----------|
| Scissor Lift | 1 | \$ 732.22 | \$ 732.22 |
| | | | \$ - |
| | | | \$ - |

PM WO History:

| |
|--|
| |
|--|

Estimate Summary:

| Labor | Material | Equipment |
|----------|------------|-----------|
| \$800.00 | \$6,608.00 | \$732.22 |

| Sub Total | G&A 12% | Fee 6% | Total Estimate |
|------------|----------|----------|----------------|
| \$8,140.22 | \$976.83 | \$488.41 | \$9,605.46 |