

Date:

Region:
FAC ID:

FEMS/CSS No.:
Maximo WO No.:

Asset #:

Priority:



Original Work Request:

High bay door #13 has a broken cable and is in the up position. Manager is having a forklift put under it so it does not fall.

Description of Repairs Needed:

Proposal includes emergency service to investigate and secure door, and identify equipment and materials needed for repair.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2) - Investigation (Emergency)	4	\$ 157.81	\$ 631.24
			\$ -

Material List:

	Quantity	Cost	Total
Misc Materials (shop supplies)	1	\$ 11.48	\$ 11.48
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$631.24	\$11.48	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$642.72	\$77.13	\$38.56	\$758.41