

Date: 11-06-25

Region: 4A

FEMS/CSS No.: 2965980

FAC ID: PA118

Maximo WO No.: 19786

Asset #:

Priority: 3



Original Work Request:

Perform preventative maintenance on wash rack recycler per manufactureres recommendations.

Description of Repairs Needed:

PM performed per manufacturers recommendations

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	4	\$ 125.00	\$ 500.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
Misc	1	\$ 44.40	\$ 44.40
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
Truck Charge	1	\$ 240.00	\$ 240.00
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$500.00	\$44.40	\$240.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$784.40	\$94.13	\$47.06	\$925.59