

Date: 1-15-25

Region: 4A

FAC ID: PA118

FEMS/CSS No.: 2992599

Maximo WO No.: 17901

Asset #:

Priority: 2



Original Work Request:

Large tree fell on the fence. Tree will need to be cut up and removed as well as several sections of fencing, barbed wiring and extension arms need to be repaired. Fence line will need replacing to include fence fabric, barbed wire, and extension arms.

Description of Repairs Needed:

Cut and remove fallen tree and repair damaged fence line to bring back up to current standard. Anticipate project lasting 2-3 days depending on weather.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (multiple)	40	\$ 85.00	\$ 3,400.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
fencing, barb wire, fence fabric and extension arms	1	\$ 1,892.43	\$ 1,892.43
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$3,400.00	\$1,892.43	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$5,292.43	\$635.09	\$317.55	\$6,245.07