

Date: 10-8-25

Region: 4A

FAC ID: PA118

FEMS/CSS No.: 3114231

Maximo WO No.: 18905

Asset #:

Priority: 3



Original Work Request:

Repair exhaust hoses in AMSA bldg and Warehouse. There is one exhaust hose reel that is not allowing the hose to come down in Bay#2 of the AMSA and there is one in the Warehouse that will not allow the hose to coil up. A lift is needed for these repairs.

Description of Repairs Needed:

Proposal is to repair the hose reel at PA118 in both the AMSA and Warehouse buildings.

Labor:	Labor Hrs	Labor Rate	Total
Tech (2) - Investigate	7	\$ 170.00	\$ 1,190.00
Trip Charge - Investigate	1	\$ 95.00	\$ 95.00
Tech (2) - Repair	16	\$ 170.00	\$ 2,720.00
Trip Charge - Repair	1	\$ 95.00	\$ 95.00

Material List:	Quantity	Cost	Total
Spring Cassette Kit (00000112492)	1	\$ 3,240.00	\$ 3,240.00
Freight	1	\$ 60.00	\$ 60.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
Scissor Lift - Investigate	1	\$ 163.00	\$ 163.00
Scissor Lift - Repair	1	\$ 163.00	\$ 163.00
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$4,100.00	\$3,300.00	\$326.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$7,726.00	\$927.12	\$463.56	\$9,116.68