

Date: 5-27-25

Region: 4A

FEMS/CSS No.: 3189884

FAC ID: PA118

Maximo WO No.: 19170

Asset #:

Priority: 3



Original Work Request:

The monitor for the CAC system in Rm 109 needs to be relocated to the wall between the cubicles as it cannot be seen where it is presently located. Also repair the 3 CAC reader hood shields. One for the unit located at the main gate from the POV lot and 2 on the AMSA building. Picture attached of the type cover needed.

Description of Repairs Needed:

Proposal is the move CAC monitor and add weather shields at the locations identified in the SOW.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	30	\$ 95.00	\$ 2,850.00
Administrative	1	\$ 100.00	\$ 100.00
			\$ -

Material List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

Equipment List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$2,950.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,950.00	\$354.00	\$177.00	\$3,481.00