

Date: 1-5-26

Region: 4A

FEMS/CSS No.: 3462327

FAC ID: PA118

Maximo WO No.: 20943

Asset #:

Priority: 2



Original Work Request:

Pump approximately 9000 gal from tanks of the oil/water separator and pressure wash tank that is located between the AMSA and Wash Rack. There are 3 tanks that will need to be cleaned and pumped out.

Description of Repairs Needed:

This initial proposal is for evaluation and lab analysis of the contents. Once the lab analysis is received, vendor will provide a quote for removal of 9000 gal and pressure washing.

Labor:

	Labor Hrs	Labor Rate	Total
Lab Aanlysis	1	\$ 750.00	\$ 750.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

Equipment List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$750.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$750.00	\$90.00	\$45.00	\$885.00