

Date: 1-8-26

Region: 4A

FEMS/CSS No.: 3462327

FAC ID: PA118

Maximo WO No.: 20943

Asset #:

Priority:  1



**Original Work Request:**

Pump approximately 9000 gal from tanks of the oil/water separator and pressure wash tank that is located between the AMSA and Wash Rack. There are 3 tanks that will need to be cleaned and pumped out.

**Description of Repairs Needed:**

Proposal is to perform lab analysis of OWS contents and pump ~9000 gal from tank of the OWS and pressure wash tank that is located between AMSA and Wash Rack. There are also 3 tanks that will be cleaned and pumped out. Rates are itemized by labor, equipment and supplies on a project basis along with separate cost for disposal.

**Labor:**

	Labor Hrs	Labor Rate	Total
Lab Aanalysis	1	\$ 750.00	\$ 750.00
Tech (4)	46	\$ 63.28	\$ 2,911.00
			\$ -

**Material List:**

	Quantity	Cost	Total
supplies (cam locks, Tyveks, gloves, duct tape, etc)	1	\$ 119.00	\$ 119.00
Disposal (up to 9000 gal liquied, 12 tons solids)	1	\$ 8,848.00	\$ 8,848.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

**Equipment List:**

	Quantity	Cost	Total
vacuum truck, pressure washer, service truck	1	\$ 4,031.72	\$ 4,031.72
			\$ -
			\$ -

**PM WO History:**

--

**Estimate Summary:**

Labor	Material	Equipment
\$3,661.00	\$8,967.00	\$4,031.72

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$16,659.72	\$1,999.17	\$999.58	\$19,658.47