

Date: 1-7-26

Region: 4A

FEMS/CSS No.: 3462327

FAC ID: PA118

Maximo WO No.: 20953

Asset #:

Priority: 2



Original Work Request:

Pump ~9000 gal from tanks of the OWS and pressure wash tank that is located between the AMSA and Wash Rack. There are 3 tanks that will need to be cleaned and pumped out. Recommended contractor Saracon

Description of Repairs Needed:

Proposal is to pump ~9000 gal from tank of the OWS and pressure wash tank that is located between AMSA and Wash Rack. There are also 3 tanks that will be cleaned and pumped out. Rates are itemized by labor, equipment and supplies on a project basis along with separate cost for disposal.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (4)	46	\$ 63.28	\$ 2,911.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
Supplies (cam locks, Tyveks, gloves, duct tape, etc)	1	\$ 119.00	\$ 119.00
Disposal (up to 9000 gal liquied, 12 tons solids)	1	\$ 8,848.00	\$ 8,848.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
vacuum truck, pressure washer, service truck	1	\$ 4,031.72	\$ 4,031.72
			\$ -
			\$ -

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$2,911.00	\$8,967.00	\$4,031.72

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$15,909.72	\$1,909.17	\$954.58	\$18,773.47