

Date: 01-14-26

Region: 4A

FEMS/CSS No.: 3462444

FAC ID: PA118

Maximo WO No.: 21178

Asset #:

Priority:  3



**Original Work Request:**

Two of the exhaust hoses are torn in the warehouse and need to be replaced

**Description of Repairs Needed:**

Replace damaged hose with new. Will reuse current hose clamps to minimize cost. Supplier notes that the hose is on backorder until mid February.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	4	\$ 100.00	\$ 400.00
			\$ -
			\$ -

**Material List:**

	Quantity	Cost	Total
Ducting Hose 12' (0212045000001)	1	\$ 495.00	\$ 495.00
Freight	1	\$ 25.00	\$ 25.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

**Equipment List:**

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$400.00	\$520.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$920.00	\$110.40	\$55.20	\$1,085.60