

Date: 3-21-24

Region: 4A  
FAC ID: PA209

CSS No.: 96640  
Maximo WO No.: 15009

Asset #:

Priority: 3



**Original Work Request:**

Repair two pole lights that are out on the bin by the dumpster going to the motor pool. Recommended vendor:  
Tambe Electric

**Description of Repairs Needed:**

Replace 2 - 110w Keystone lamps at dumpster area near Motor Pool. Bucket truck will be required.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (2)	4	\$ 105.00	\$ 420.00
			\$ -

**Material List:**

	Quantity	Cost	Total
110w Lamps (#KT-LED110HID-H-EX39-850-D/G3)	2	\$ 220.32	\$ 440.64
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

**Equipment List:**

	Quantity	Cost	Total
Bucket Truck	3	\$ 105.00	\$ 315.00
		\$	-
		\$	-

**PM WO History:**



**Estimate Summary:**

Labor	Material	Equipment
\$420.00	\$440.64	\$315.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,175.64	\$141.08	\$70.54	\$1,387.26