

Date: 1-26-25

Region: 4A

FAC ID: PA209

FEMS/CSS No.: 99025

Maximo WO No.: 17946



Asset #:

Priority: 3

**Original Work Request:**

Repair interior and exterior doors. Training Building - repair hardware o door to Assembly Hall (Rm 145), door to Admin Area, Door to Gym (Rm 115) and exterior door by Rm 111. OMS Bldg: Repair door to Admin Area from bays and door to office. They need to be grinded as theyare not functioning properly and finished. Paint color for doors is sW-2847 Roy Croft Bottle Green. Recommended Contractor: Troy Construction (724) 421-5193

**Description of Repairs Needed:**

Repair interior and exterior door. Training Building - repair hardware o door to Assembly Hall (Rm 145), door to Admin Area, Door to Gym (Rm 115) and exterior door by Rm 111. OMS Bldg: Repair door to admin Area from bays and door to office (B-105). The y need to be grinded as they are not functining properly and finished. Pain color for doors is SW-2847 Roy Croft Bottle Green.

Labor:	Labor Hrs	Labor Rate	Total
Tech (3)	24	\$ 100.00	\$ 2,400.00
			\$ -
			\$ -

Material List:	Quantity	Cost	Total
Hardware Mechanism	8	\$ 700.00	\$ 5,600.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

**PM WO History:**

--

**Estimate Summary:**

Labor	Material	Equipment
\$2,400.00	\$5,600.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$8,000.00	\$960.00	\$480.00	\$9,440.00