

Date: 12-03-24

Region: 4A

FAC ID: PA209

FEMS/CSS No.: 2935159

Maximo WO No.: 17085



Asset #:

Priority: 2

Original Work Request:

Repair leaking actuator for the hot water heating. The actuator is leaking in the mechanical room next to AS-1.

Description of Repairs Needed:

Proposal is the replace the leaking actuator valve on the hot water heating

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	8	\$ 156.00	\$ 1,248.00
Trip Charge	1	\$ 180.00	\$ 180.00
			\$ -

Material List:

	Quantity	Cost	Total
Actuator Valve (Item 20XH89, Mfr Model V-4000-1)	1	\$ 393.00	\$ 393.00
Piping Materials	1	\$ 236.00	\$ 236.00
freight	1	\$ 35.00	\$ 35.00
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$1,428.00	\$664.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,092.00	\$251.04	\$125.52	\$2,468.56