

Date: 1/15/25

Region: 4A

FAC ID: PA209

FEMS/CSS No.: 2992566

Maximo WO No.: 17910



Asset #:

Priority: 3

**Original Work Request:**

Repair ice machine located in kitchen

**Description of Repairs Needed:**

Proposl is to descale and clean ice machine, including solenoid, and replace with new water filter. Per Tech, RFOS wants to change PM to quarterly instead of every six months for this site.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	3.5	\$ 100.00	\$ 350.00
			\$ -
			\$ -

**Material List:**

	Quantity	Cost	Total
Manitowoc filter (AR-10000-P Artic Pure Plus)	1	\$ 290.00	\$ 290.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

**Equipment List:**

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

**PM WO History:**

--

**Estimate Summary:**

Labor	Material	Equipment
\$350.00	\$290.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$640.00	\$76.80	\$38.40	\$755.20