

Date: 12-23-25



Region: 4A

FEMS/CSS No.: 3432941

FAC ID: PA209

Maximo WO No.: 20934

Asset #:

Priority: 3

Original Work Request:

OMS urinal on the right is leaking from the back of the unit and needs to be repaired. Also the flush valves on the urinals in the training Center need to be cleaned, four in all.

Description of Repairs Needed:

Replace one urinal that's cracked in the OMS and clean flush valves on 4 urinals in the Training Center

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	4	\$ 100.00	\$ 400.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
Urinal (6590.001.020)	1	\$ 175.00	\$ 175.00
freight	1	\$ 30.00	\$ 30.00
Misc (shop supplies, cleaners, rags, etc.)	1	\$ 50.00	\$ 50.00
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$400.00	\$255.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$655.00	\$78.60	\$39.30	\$772.90