



Proudly serving the entire states of Virginia & North Carolina.

Altavista, VA • Charlottesville, VA • Chesapeake, VA • Christiansburg, VA

Falmouth, VA • Lynchburg, VA • Richmond, VA • Greensboro, NC

P.O. Box 119 • Altavista, VA • 800.789.7199 • service@mooreselectric.com

Billing Address	Site Address
Customer: INTERNATIONAL SUPPORT GROUP Address: 9000 SHERIDAN ST Phone: PEMBROKE PINES FL 33024 954-900-1095	Customer: ISA USARC VA049 CHESTERFIELD Address: 6700 STRATHMORE ROAD Phone: NORTH CHESTERFIELD VA 23237 8045855211
Service Call #: COM0116572	Call Type: COM-PM


Service Requested
SEPTEMBER PM
PM FOR HVAC
THIS IS A TIME AND MATERIAL PM, SO THERE ARE NO SPECIFIC HRS.
SEE CODE 35 FORM FOR HOW MANY PIECES ARE ON SITE TO PM. EX-10100 1599 PM-QT-1599 J-1502000-27 1-pc Water Heater Break Room (THERE IS 1 PIECE OF EQUIP)
CODE 35 AND COW
ANY ADDITIONAL WORK NEEDED OUTSIDE THE SCOPE ON THE FORM, PLEASE TAKE PHOTOS, DOCUMENT IN SERVICE NOTES, AND SUBMIT A QUOTE.

Problems					
Description	Tech	Equip. Desc and Model	Manufacturer	Equip. Serial	Asset ID
Commercial Planned Maintenance	JEREMYGRAY	ALL HVAC UNITS	Generic		
Commercial Planned Maintenance	MIKE CIMINO	unit# 6 M# 38YCC036530	Carrier	2800E31041	

Tech Notes
Site Start - 9/13/2019 10:45 AM Site Stop - 9/13/2019 2:00 PM ONCE I GOT AHOOLD ON THE SITE CONTACT STARTED TO LOOK FOR THE EQUIPMENT
Site Start - 10/8/2019 3:00 PM
Site Stop - 10/8/2019 5:00PM
Located AHU and replaced return air filter.
Tech: Michael Cimino, Date: 10/8/19 5:00 PM - All planned maintenance tasks and required forms completed on all units.

Labor			
Date Technician Description Hours			
9/13/2019	Peter Langston	REGULAR HVACR LABOR	2.75
9/13/2019	Peter Langston	REGULAR HVACR LABOR	0.50
10/8/2019	Michael Cimino	REGULAR HVACR LABOR	2.00

Materials
Date Part Number Description Quantity
No records found

Signed By	N/A	Signature		Date	10/8/2019
------------------	-----	------------------	--	-------------	-----------