



Proudly serving the entire states of Virginia & North Carolina.

Altavista, VA • Charlottesville, VA • Chesapeake, VA • Christiansburg, VA

Falmouth, VA • Lynchburg, VA • Richmond, VA • Greensboro, NC

P.O. Box 119 • Altavista, VA • 800.789.7199 • service@mooreselectric.com

Billing Address	Site Address
<b>Customer:</b> INTERNATIONAL SUPPORT GROUP <b>Address:</b> 9000 SHERIDAN ST <b>Phone:</b> PEMBROKE PINES FL 33024 954-900-1095	<b>Customer:</b> ISA USARC VA049 CHESTERFIELD <b>Address:</b> 6700 STRATHMORE ROAD <b>Phone:</b> NORTH CHESTERFIELD VA 23237 8045855211
<b>Service Call #:</b> COM0116575	<b>Call Type:</b> COM-PM

Service Requested
SEPTEMBER PM PM FOR FLOOD LIGHT POLE THIS IS A TIME AND MATERIAL PM, SO THERE ARE NO SPECIFIC HRS. SEE CODE 35 FORM FOR HOW MANY PIECES ARE ON SITE TO PM. EX-10100 1599 PM-QT-1599 J-1502000-27 1-pc Water Heater Break Room (THERE IS 1 PIECE OF EQUIP) CODE 35 AND COW ANY ADDITIONAL WORK NEEDED OUTSIDE THE SCOPE ON THE FORM, PLEASE TAKE PHOTOS, DOCUMENT IN SERVICE NOTES, AND SUBMIT A QUOTE.

Problems
Description Tech Equip. Desc and Model Manufacturer Equip. Serial Asset ID Commercial Planned Maintenance PETELANGST POLE LIGHTS Generic

Tech Notes
Site Start - 9/27/2019 8:00 AM Site Stop - 9/27/2019 11:30 AM ARRIVED ON SITE THERE ARE 18 POLES LIGHTS .CHECKED POLES TO SEE IF WHICH 7 POLE LIGHTS WHERE TAGGED. NONE WHERE TAGGED. PICKED 7 CLOSEST LIGHTS TO THE MAIN BUILDING. CHECKED ELECTRICAL CONNECTIONS, COMPLETED TASKING FORM.

Labor
Date Technician Description Hours 9/27/2019 Peter Langston REGULAR HVACR LABOR 3.50

Materials
Date Part Number Description Quantity No records found

Signed By	Sean Miles	Signature		Date	9/27/2019
-----------	------------	-----------	--	------	-----------