

Service Items

Name	Description	Tier 1 Price	Unit Type	QTY	Taxable
Labor	See attached pages for details of work performed.	\$0.00	Hour	1	N
TOTAL*:	\$0.00				

* Not including taxes




Service Forms

Daily Form	Fill out every day, even on PMs, and projects
TECH NAME	Tom Timlin
DATE	1/23/23
TOOLS USED	hand tools
MATERIALS USED	2: munchkin control boards 2: Wiring harness (All ordered by Ryan)
DESCRIPTION OF WORK PERFORMED	Removed the old control board from B-2 and installed the new one with a new wiring harness. Made sure everything was wired back in properly and test ran B-2. Removed the old board from B-1 and installed the new board with wiring harness. Test ran B-1 to make sure it was still running properly and it was. Took a combustion test on B-2 and had to make a slight adjustment to the gas valve to get it running where it should be. Both boilers are running good at this time.
HOURS	REGULAR:
	OVERTIME:




Attachments

Title	File Name
1-23-23 Franklin Boiler control boards	1-23-23 Franklin Boiler control boards.pdf
B-2 When leaving	a8aa69e8-4779-4f4f-9f6a-ee73b7b76c50.jpg




B-2 Before

f4e5fca1-820b-43eb-8d52-1d5c6c55c7b9.jpg




B-1 Before

0752ae4f-0cd5-44b0-b23d-4b0ceba0596f.jpg




B-2 After

e56995f3-6b44-4cf1-94b0-6bfa88be7cfc.jpg




B-2 After

bdd60021-b4e6-47a2-ac0d-a9276c187492.jpg




B-1 Before

107200ef-2f62-4411-bece-c3f1e9f22431.jpg




B-2 Combustion test

595ce7fe-4961-4bf9-91f4-2fa43c012dab.jpg




B-1 After

1618ab84-943a-4912-95de-417606dec91a.jpg



B-2 Before

abc3dcf0-1fe4-4677-aa82-eee85ee8d0e7.jpg



CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: PA035 Date of Visit: 1/23/23

Contractor Personnel on Site:

1. Tom Timlin 2. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. _____

Service Calls – Service Call Number and Description

1. CSS# 90989. Control Boards for Boilers 1&2
2. CSS# _____
3. CSS# _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Thomas Timlin Date: 1/23/23

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, I certify that the above-named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed. This is NOT a Certification that the Work was performed correctly – The COW simply verifies that that someone representing the Contractor was onsite and accomplished something

Print Name/Rank: Cynthia Croyle/ AFOS Date: 12/13/22

Signed: 

E-Mail: cynthia.a.croyle.ctr@army.mil