



Date: 06/21/2023

Region: 4C
FAC ID: WV035

CSS No.: 90111
Maximo Work Order No.: 12510

Original Work Request:

Replace release valve on Apex Boiler #4. It's failing due to the system being down for so long.

Description of Repairs Needed:

Investigation to diagnose issue with relief valve not working. Reported that the system has been down for an extensive time and valve not working.

1 technician (investigation 2.5 hrs @ \$125/hr); Travel Time \$125.00

CMI markup 15%

Materials List:

NA

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	CMI Markup 15%	Total Repair
2.5	437.50	\$65.00	\$502.50

