

Date: 6/27/2023

Region: 4A  
FAC ID: NY126

CSS No.: 93900  
Maximo WO No.: 13037



Asset #:

Priority:  Urgent

**Original Work Request:**

Perform backflow inspection for 3 each backflow devices 2 backflows for the domestic water

**Description of Repairs Needed:**

Labor and material to perform (3) backflow inspections.  
Please note if further repairs are needed we will request a follow up ticket.

**Labor:**

	Labor Hrs	Labor Rate	Total
Technician	3	\$ 100.00	\$ 300.00
			\$ -

**Material List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

**Equipment List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

**PM WO History:**

NA

**Estimate Summary:**

Labor	Material	Equipment
\$300.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$300.00	\$36.00	\$18.00	\$354.00