

Date: 9/21/2023

Region: 4A

CSS No.: 94652

FAC ID: NY070

Maximo WO No.: 13643

Asset #: NA

Priority: Routine



Original Work Request:

Replace non-functioning emergency sign. The sign does not stay lit when tested.

Description of Repairs Needed:

Labor and material to a.) remove the exit signs that are not functioning correctly b.) install new signs and test for proper operation

Labor	Labor Hrs	Labor Rate	Total
Technician	6	\$ 100.00	\$ 600.00
		\$ -	\$ -

Material List:

Ext Sgn,Alum,Blk,11 3/8in,4W LITHONIA LIGHTING LE S 2 R EL N SD	Quantity	Cost	Total
	2	\$ 286.46	\$ 572.91
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$600.00	\$ 572.91	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,172.91	--	--	\$1,172.91

Note: G&A and Fee are not applied on top of work performed by Tidewater.



Prepared by:

Tidewater, Inc.
6625 Selknick Drive, Suite A
Elkridge, MD 21075

Prepared for:

CMI Management, Inc.
5285 Shawnee Road Suite 510
Alexandria, VA 22312-2334

Date: 9/21/2023
FAC ID: NY070

CSS #: 94652
WO #: 13643

DESCRIPTION OF WORK			
Labor and material to a.) remove the exit signs that are not functioning correctly b.) install new signs and test for proper operation			

LABOR	QTY	UNIT/RATE	TOTAL
Technician	6	\$100.00	\$600.00
		\$0.00	\$0.00
MATERIAL	QTY	UNIT/RATE	TOTAL
Ext Sgn,Alum,Blk,11 3/8in,4W LITHONIA LIGHTING LE S 2 R E	2	\$286.46	\$572.91
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$600.00
	MATERIAL TOTAL		\$572.91
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			\$1,172.91

Accepted By: _____

Date: _____

EXIT

Please use
Main Entrance
located at the
front of the
building

EXIT