

Date: 10/30/2023

Region: 4A

CSS No.: 95484

FAC ID: NY126

Maximo WO No.: 14270

Asset #: NA

Priority: Routine



Original Work Request:

Troubleshoot lighting circuit with infrared imaging, to check for "hot wires" in transformer boxes. Last electrician suggested this may locate issues with lighting circuit.

Description of Repairs Needed:

Labor and material to a.) Conduct an IR scan of electrical equipment and provide report.

Labor:

	Labor Hrs	Labor Rate	Total
Technician	8	\$ 125.00	\$ 1,000.00
			\$ -

Material List:

	Quantity	Cost	Total
IR Scan Service	1	\$ 2,500.00	\$ 2,500.00
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$1,000.00	\$ 2,500.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$3,500.00	\$420.00	\$210.00	\$4,130.00

Estimate #2484

10/30/2023

Karlee Demain

(724) 678-6067

karlee.demain@tideh2o.net

Tidewater, Inc.

5835 Avenida Encinas, Suite 118

Carlsbad, CA 92008



Site: US Army Corps Reserve, 49 Jetview Drive, Rochester, NY 14624

We are pleased to submit the quotation for the following:

JOB: IR SCAN

Conduct an IR scan of electrical equipment and provide report.

* Cost is based on work being done during normal business hours Mon-Fri, 6am - 6pm. * Cost is based on job being prevailing wage and tax exempt.

This quote is based on the information provided and on the walk-through at the facility. Installation as per NEC, Tidewater, Inc. standards and specifications provided.

Tambe Electric Inc., their associates, employees and those under contract of Tambe Electric Inc. are not responsible or liable for any losses or personal injury to any entity as a result of; mislabeling/misidentification or errors on drawings, panel schedules, existing circuit/raceway installations, existing conditions or otherwise unknown factors.

Upon issuance of PO and after material delivery, allow (10) business days for equipment delivery. Not responsible for delays or costs incurred due to labor strikes, natural disasters, acts of God or other like circumstances. Quote subject to final approval of scope of work and final BOM. Due to the volatility of market prices on materials and freight, total cost may need to be increased depending on when quote is accepted by customer.

The total cost of this installation is:

PW Labor: 8hrs @ 125.00 = \$1,000

IR Scan Service: \$2,500.00

Total: \$3,500.00

Thank you for the opportunity!

Martin Johnson

Service Manager/Estimator

Tambe Electric Inc.

M: 585-645-2252

P: 585-924-8700

F: 585-924-8771

mjohnson@tambeelectric.com

614 Fishers Run, Victor, NY 14564

To approve please click on red link from email, sign/date and return quote or send PO:

Approved:

Signed by customer _____

Date _____