

Date: 7/27/2023

Region: 4C
FAC ID: WV009

CSS No.: 94154
Maximo WO No.: 13425

Asset #: NA

Priority: Routine



Original Work Request:

Repair roll up door on storage building

Description of Repairs Needed:

Labor and material to a.) to install storage boxes in back broken springs on roll up doors 6x7 DBCI

Labor:	Labor Hrs	Labor Rate	Total
Technician 2 Men	5	\$ 90.00	\$ 450.00
Service Call	1	\$ 85.00	\$ 85.00

Material List:	Quantity	Cost	Total
Diagnostic Fee	1	\$ 150.00	\$ 150.00
Mini Warehouse Springs	4	\$ 80.00	\$ 320.00
		\$ -	\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 535.00	\$ 470.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,005.00	\$120.60	\$60.30	\$1,185.90

American Garage Door, LLC Phone 304-592-0936
6909 Shinnston Pike Fax 304-592-3430
Shinnston, WV 26431

Invoice No. **estimate**

INVOICE

Customer

Name Tidewater, Inc.
Address 6625 Selnick Dr., Suite A
City Elkridge State MD ZIP 21075
Phone 410-540-8700

Misc

Date 7/25/2023
Cust PO
Rep AJ
FOB

Qty	Description	Unit Price	TOTAL
	Clarksburg, WV Armory storage boxes in back broken springs on roll up doors 6x7 DBCI		
4	mini warehouse springs	\$ 80.00	\$ 320.00
1	Service Call	\$ 85.00	\$ 85.00
5	Commercial Hours Labor 2 men	\$ 90.00	\$ 450.00
1	Diagnostic Fee 7-24-23	\$ 150.00	\$ 150.00
SubTotal			\$ 1,005.00
Shipping			
Tax Rate(s) 6.00%			\$ 60.30
TOTAL			\$ 1,065.30

Payment

Select One...

Comments
Name
CC #
Expires

Tax Rate(s)

Office Use Only

Payment Due Upon Job Completion! 1.5% Per Month Interest Charges Will Incur After 30 Days!

Thanks