

Date: 10/9/2023

Region: 4A
FAC ID: NY052

CSS No.: 95059
Maximo WO No.: 14064



Asset #: NA

Priority: Urgent

Original Work Request:

Repair air receiver. Make: Melben Model: KN-6 Serial: 1008535.

Description of Repairs Needed:

Labor to a.) to troubleshoot the air receiver. Make: Melben Model: KN-6 Serial: 1008535.

Labor:

	Labor Hrs	Labor Rate	Total
Technician	3	\$ 128.00	\$ 384.00
Trip Charge	1	\$ 50.00	\$ 50.00

Material List:

	Quantity	Cost	Total
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 434.00	\$ -	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$434.00	\$52.08	\$26.04	\$512.12



October 4, 2023

Tidewater
US Army Corps of Engineers
3126 Lake Rd
Horseheads, NY 14845

Attn: Karlee Demain

Re: Troubleshoot Melben KN-6 to plan repairs

Ms. Demain,

Postler & Jaeckle Service is pleased to provide a quote to troubleshoot a Melben KN-6 air receiver to plan repairs at your PennYan location. Your cost for this will be \$384.00 labor and \$50.00 trip charge for a total of \$434.00 plus any applicable taxes. This quote does not include repairs. If repairs are required another quote will be prepared for your approval. This quote is based on work being performed during normal working hours of 8:00am to 4:30pm Monday through Friday. Thank you for the opportunity to provide this quote for your facility. Please contact me with any questions.

Sincerely,

DAVE HENDEE
Field Sales Support
Postler & Jaeckle Corp.
2000 Lake Rd., Elmira, NY 14903
T 607-739-8303 | C 607-215-6523
E: dhendee@postler.com