

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: PA 096 Date of Visit: 8-6-19

Contractor Personnel on Site:

1. Bernard Koblinsky
2. _____
3. _____
4. _____
5. _____
6. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. _____
2. _____
3. _____
4. _____

Inspection, Testing, and Certification

QC

1. CSS# 15129 ICE MACHINE "PASSED"
2. CSS# 17181 RESTROOM EXHAUST FANS "PASSED"
3. _____
4. _____

Other Recurring Services

1. _____
2. _____
3. _____
4. _____

Service Calls – Service Call Number and Description

1. _____
2. _____
3. _____

PD 096

Over and Above Repair Work -- Order Number and Description of Work Completed

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Bernard Koblinsky Date: 8-6-19
Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: HANNAH FLORIAN GS-09 Date: 8-6-19
Signed: Hannah Florian
E-Mail: hannah.l.florian.civ@mail.mil

SERVICE CALL COMPLETION AND STATUS REPORT
Contract Number: W912BU17F0091 (Region 4)

Report Date: July 31, 2019
Option Period 1: CLIN 1002

Invoice For The Month Of: July 2019
Temp for review

WO #	FAC ID	No.	Site Code	CLIN	CSS #	Zone	Stack ed Amount	Stacked Amount Sub Total	Description of Repairs Completed	Date Completed	Authorized By
									nt by Site		
8151	NY126-01	36917	1002-A1	17767	A2	7			CSS 17767-NY126: Motorized gate to MEP has broken bearing assembly on chain drive	11-Jul-19	Scott Kawska
8152	NY126-01	36917	1002-A1	17768	A2	7			CSS 17768-NY126: Make repairs to gate rollers on manual drive through gate	11-Jul-19	Scott Kawska
8422	NY126-01	36917	1002-A1	16897	A2	4			PWCO 6843: New WCO opened for additional work needed on concrete door in CMS	19-Jul-19	Scott Kawska
8071	MD008-01	24715	1002-AA	17348	B5	1			CSS 17348-MD008-Urgent: Both air handlers units located in classroom of training buil	03-Jul-19	Jason Belcher
5148	MD008-02	24715	1002-AA	14899	B5	1			Needs new weatherstripping	17-Jul-19	Jason Belcher
7462	PA020-01	42840	1002-AO	16465	B5	14			Jason Belcher: PA020-01, Urgent: Repair leaking boiler make-up water	03-Jul-19	Jason Belcher
7474	PA053-02	42380	1002-AQ	16927	B5	1			Asset 4513 Unit Heater: Gas line/Radiant gas pressure regulator is too high	03-Jul-19	Jason Belcher
8767	PA096-01	42965	1002-BD	15128	B5	12			Asset # 6838: 1-pc valve Maker: Hotel/Fire Machine with Storage Bn - Not working	15-Jul-19	Scott Kawska
8166	PA096-01	42965	1002-BD	17181	B5	6			CSS 17181-PA096-Routine: Exhaust fans located in both the men's and women's latrin	03-Jul-19	Jason Belcher
8153	PA166-01	42671	1002-BF	17106	B5	8			CSS 17106-PA166- URGENT: Repair the following plumbing issues: 1.	05-Jul-19	Jason Belcher
8848	WW038-01	54570	1002-CF	16745	B5	1			Asset# 4176: Unit Heater: Electric. Suspended. T-stats broken, 4x4 junction box is mis	05-Jul-19	Jason Belcher
635C	WW038-01	54570	1002-CF	17388	B5	13			Asset# 4370-J-150200-08 1-pc Unit Heater: Hot Water Gate valve stuck open will not r	03-Jul-19	Jason Belcher
						57					
6821	VA001-01	51685	1002-BL	16668	C9	1			Jason Belcher: CSS 16668: VA001- Emergency: F/T McCoy detected there is no power in	26-Jul-19	Jason Belcher
8084	VA031-01	51685	1002-BL	17364	C9	1			CSS 17364: VA001- Broken Window in front office. Window is double paned this seems	17-Jul-19	Jason Belcher
4940	VA033-01	51735	1002-BO	17320	C9	1			Fan motor failed. Needs to be replaced	26-Jul-19	Jason Belcher
7159	VA033-01	51735	1002-BO	17027	C9	1			Jason Belcher: VA033-01, OSS 17027: Urgent: Crane controls not operating properly.	17-Jul-19	Jason Belcher
8052	VA033-01	51735	1002-BO	17323	C9	1			CSS 17323: VA033-Routine: Clean all diffusers, returns and change air filters.	17-Jul-19	Jason Belcher
8054	VA033-01	51735	1002-BO	17324	C9	1			CSS 17324: VA033-Routine: Gutter joints are split and leaking the entire perimeter of th	26-Jul-19	Jason Belcher
8056	VA033-01	51735	1002-BO	17326	C9	1			CSS 17326: VA033-Routine: Water penetration in room 111 & 112 Strip, Seal and Rep	26-Jul-19	Jason Belcher
8060	VA033-01	51735	1002-BO	17325	C9	1			CSS 17325: VA033-Urgent: Identify issue stated less by Room 111 & 111A FTS	26-Jul-19	Jason Belcher
8170	VA033-02	51735	1002-BO	17321	C9	1			CSS 17321: VA033-Routine: ASSET #245 NG HEAT per MSG Tech on site Min Split	17-Jul-19	Jason Belcher
5732	VA039-01	51743	1002-BP	15159	C9	1			Jason Belcher: P/M Found hot water tank leaking	26-Jul-19	Jason Belcher
6392	VA051-01	51815	1002-BQ	13556	C9	1			Jason Belcher: Remove two 8-inch female drain couplings	25-Jul-19	Jason Belcher