

ATTACHMENT J-0200000-05
FORMS

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: WV038

Date of Visit: 7-2-19

Contractor Personnel on Site:

1. A. Lazarus
2. J. Coontz
3. S. weany
4. _____
5. _____
6. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. _____
2. _____
3. _____
4. _____

Inspection, Testing, and Certification

QC

1. 17274 - RE FILLED GYCOL TANK w/ # 8124
2. _____
3. _____
4. _____

Other Recurring Services

1. _____
2. _____
3. _____
4. _____

Service Calls - Service Call Number and Description

1. _____
2. _____
3. _____


144038

Over and Above Repair Work – Order Number and Description of Work Completed

CERTIFICATION OF WORK

To be signed by the Contractor:


Print Name: Bernard Kobline Date: 7-2-19

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline.

Print Name/Rank: Shane Fabian Date: 7-2-19

Signed: 

E-Mail:

SERVICE CALL COMPLETION AND STATUS REPORT
Contract Number: W912BU17F0091 (Region 4)

Report Date: May 31, 2018
Option Period 1: CLIN 1002

Invoice For The Month Of: May 2018
Temp for review

WO #	FAC ID No.	Site Code	CLIN	CSS #	Zone	Stack ed Amount	Stacked Amount Sub-Total by Site	Description of Repairs Completed	Date Completed	Authorized By
7219	NY010-01	36830	1002-AB	17180	A2	1		Scott Kawski, Urgent, CSS 17180, NY010-1002-AB, repair faulty light switch in Siding gate directly in front of CMS.	22-May-19	Scott Kawski
7465	NY010-01	36830	1002-AB	17239	A2	1		Scott Kawski, Urgent, CSS 17239, NY010-1002-AB, Make repairs to basement exterior doors.	15-May-19	Scott Kawski
5234	NY070-01	36976	1002-AH	15053	A2	1		Scott Kawski, Repair overhead exterior eaves, rewire the bracket's broken.	15-May-19	(null)
3367	PA118-01	42856	1002-BE	12642	A2	1		Jason Belcher, Floor mounted closers on both sets of vestibule	15-May-19	Scott Kawski
5965	PA168-01	42993	1002-BG	15962	A2	1	5		15-May-19	Jason Belcher
7478	PA166-01	42671	1002-BF	17107	B5	1		Asset# 4410-Urgent: Heater, hot Water, Suspended in Stair 4, Fan motor needs replaced	10-May-19	(null)
8987	PA042-01	42860	1002-AR	19253	B5	(null)		David Latina, annual inspection of the BF device at PA042. It's for the 2nd main SN: 18759	14-May-19	David Latina
5170	PA079-01	42928	1002-BA	14732	B5	1		Jason Belcher, Repair/fixing gutters and downspouts	21-May-19	Jason Belcher
8988	PA096-01	42965	1002-BD	19252	B5	(null)		David Latina, add ref/replace R-22 to the existing chiller at PA096. Lowering fan never	16-May-19	David Latina
8124	WV038-01	54670	1002-CF	17274	B5	13		CSS 17274- WV038-Urgent: Leve of glycol in automatic feeder used for hot water loop	20-May-19	(null)
5818	WV053-01	54468	1002-CJ	115517	B5	1		Jason Belcher, Duct heating coil, multiple ceiling tiles	22-May-19	Jason Belcher
5257	WV046-01	54627	1002-CI	14558	C9	15		Jason Belcher, Currently there is a Glycol leak		
4901	VA039-01	51743	1002-BP	14342	C9	14		Jason Belcher, Repair water lines for toilet and sink in unisex	24-May-19	Jason Belcher
2640	WV022-01	54735	1002-CA	7582	C9	1		Jason Belcher, Repair gate and fence leading to Motor	24-May-19	Jason Belcher
								13-May-19	Jason Belcher	
								30		