

**PROJECT ESTIMATE**

DATE: 03/04/2020

QUOTE ID: 5173
AR CUSTOMER: CMI MANAGEMENT (#10343)
SERVICE LOCATION: US ARMY RESERVE - CMI- SITE #NY054
STREET: 5363 PERU STREET, ROUTE 9
CITY: PLATTSBURGH, NY 12901

CONTACT: JOE BAYNE - CMI
Ph:(315) 772-8801
Fax:(315) 772-6336
joe.bayne@cmimgmt.com
DATE SUBMITTED: 03/04/2020
PREPARED BY: FRASHER, LINDA

DESCRIPTION: Motor/Pump Issues

SCOPE OF WORK: Our technician made the following notes:

RI parts washer Pulled plug and started to remove pump and motor from unit. Found pump is locked. Contacted OEM about replacing pump. Went through a few step to confirm pump is locked. I was told that this will happen if unit is left to sit. It is a mild steal pump and it will rust up when not used. Also due to age of equipment parts are limited. I was also told we can try freeing up pump by removing back of motor and turning shaft manually. Used wrench to break pump free. Ran system through one complete cycle to confirm operation. Unit is up and running.

The pricing shown below covers the costs to fix the problem with the pump/motor. Please call me at extension #236 if you have any questions. Thank you.

ITEM	QUANTITY	UNIT PRICE	TOTAL
Labor Regular Time	6	\$110.00	\$660.00
Vehicle Charge	1	\$50.00	\$50.00
Total			\$710.00

SIGNATURE

PRINT NAME

DATE



PROJECT ESTIMATE

DATE: 03/04/2020

All material is guaranteed to be as specified. All work to be completed in a workmanlike manner according to standard practices. Any alteration or deviation from the above specifications involving extra costs will be executed only upon written orders, and will become an extra charge over and above the estimate. All agreements contingent upon strikes, accidents or delays beyond our control. Our technicians are covered by New York State Workers Compensation Insurance.

QUOTE VALID FOR THIRTY (30) DAYS